




CAUTION



The Meter produces a visible laser beam which emerges from the front of the Meter.

It is a Class 2 laser product in accordance with: IEC60825-1 : 2007 "Radiation safety of laser products"



+


-



Quick Reference Guide


FLUKE®

Laser Distance Meter 414D



Buttons

1. Measure/Min Max/Power On
2. Area/Volume/Indirect Measurement (Pythagoras)
3. Reference/Units
4. Plus (+)/Minus(-)
5. Clear/Off



Default = 0'00" 1/16




1x (2 sec.) = --- in




2x (2 sec.) = --- m


Area
Volume
Height $1x = \square$




Area
Volume
Height $2x = \square$



Area
Volume
Height $3x = \triangle$



Area
Volume
Height $4x = \triangle$



Measure

